# **Asteroom Property Data Collection**



1. Information		
File #	Case File ID	Property Type
PDC_160	88888888	Single Family
Occupancy	Lock Box	Quality of Construction Rating
Yes	No	Q2
Condition Rating	Repair Estimate	
C2	0	
	0	
Address		
	0 Property Street Address (unit #)	Property City
Address		Property City Tigard
Address Property Street Address		

#### Photo(s)



2. Site		
Lot Size	Lot Size Estimate?	
7500 sqft	Yes	
Road Type	Road Maintained Indicator	Year-Round Access Indicator
Public	No	Yes

Street Photos

#### Street Left

Photo

## Street Right

Photo





View Type		
Primary View	Quality	Description
Power Lines	Partial	Power line near the house

Secondary View
Mountain Range

Quality Partial

## Description

See mountain ranges from the front of the house

Photo(s)

Photo(s)



## Location Type

Туре	Description
Residential	Residential community
Туре	Description
Adjacent to Power Lines	House is located right next to a power line tower

## Photo(s)



## **Eletrical Service**

Service Type

Public

Photo(s)



## Water Services

Service Type

Public

**Sewer Services** 

Service Type

Source of utility

Private

Septic Shared

## **Adverse Site Conditions**

Nothing Notable

## Site Improvement

Туре

Description

Fence

Fence

#### Photo(s)



Туре

Description

**Tile Patio** 

Patio

#### Photo(s)



**Non-Residential Use** 

None Observed

3. Exterior and Interior	
3.1 Exterior	
Structure Type	Construction Type
Dwelling	Frame
Construction Status	
Complete	
Attachment Type	
Detached	
Year Built	Is year built an estimate?
2004	No

#### **Structure Exterior Feature**

#### Deck

Photo(s)



## **Exterior Update**

None

## **Exterior Deficiencies**

None Observed or Reported

#### 3.2 Interior

Uniform Heating and Cooling Indicator

#### Yes

## Heating Type

#### **Central Hot Air**

Photo



## **Cooling Type**

**Central Air-Conditioning** 

Photo



#### **Mechanical Deficiencies**

None Observed

**3.3 Exterior Photos** 

Structure Front Photo(s)



## Structure Rear Photo(s)



Structure Left Side Photo(s)



Structure Right Side Photo(s)



#### View Front Photo(s)



View Rear Photo(s)



View Left Side Photo(s)



#### View Right Side Photo(s)



## 4. Improvements - Rooms

Bathroom 2

#### **Room Features**

None

#### **Room Fixtures**

Sink, Toilet, Tub/Shower

#### Room Update Type

None Observed

## Room Deficiency Type

None Observed

#### Additional Photos



### Bedroom 2

**F1** 

#### **Room Features**

None

## Room Update Type

None Observed

## Room Deficiency Type

None Observed

#### Additional Photos





**Dining Room** 

**Room Features** 

## Room Update Type

None Observed

## Room Deficiency Type

None Observed

#### Additional Photos





## Family Room

## **Room Features**

## Fireplace

Photo(s)




Room Update Type

## Room Deficiency Type

None Observed

#### Additional Photos



## Foyer

#### **Room Features**

None

## Room Update Type

None Observed

## Room Deficiency Type

None Observed

Additional Photos





## Kitchen Room Features None

#### **Room Fixtures**

Sink, Appliance Hookup

## Room Update Type

## **Cabinets Countertops**

Update Type	Timeframe	Description
Replaced	2-5	Entire Kitchen remodeled in 2019

#### Photo(s)



## Appliances

Update Type

Replaced

Timeframe

2-5

Description

Entire Kitchen remodeled in 2019 with new appliances

#### Photo(s)



## Room Deficiency Type

None Observed

#### Additional Photos



## Living Room

#### **Room Features**

None

## Room Update Type

None Observed

## **Room Deficiency Type**

None Observed

#### Additional Photos





#### Bathroom 3

## **F2**

#### **Room Features**

None

#### **Room Fixtures**

Double Sink, Toilet, Tub/Shower

#### **Room Update Type**


None Observed

## Room Deficiency Type

None Observed

#### Additional Photos





#### **Bedroom 3**

#### **Room Features**

None

**Room Update Type** 

None Observed

#### **Room Deficiency Type**

None Observed

Additional Photos





#### **Bedroom 4**

**F2** 

**Room Features** 

None

## Room Update Type

None Observed

#### **Room Deficiency Type**

None Observed





## Bedroom 5

#### **Room Features**

None

## Room Update Type

None Observed

## Room Deficiency Type

None Observed

#### Additional Photos





## Bedroom 6

**F2** 

**F2** 

**Room Features** 

None


**Room Update Type** 

None Observed

## Room Deficiency Type

None Observed

#### Additional Photos



#### Laundry Room

**Room Features** 

None

#### **Room Fixtures**

Laundry Hookup

## Room Update Type

None Observed

#### **Room Deficiency Type**

None Observed

Additional Photos





**F2** 

## **Primary Bathroom**

#### **Room Features**

None

#### **Room Fixtures**

Double Sink, Walk-In Shower, Tub w/No Shower

## Room Update Type

## Flooring

Update Type	Timeframe	Description
Replaced	2-5	Entire primary bathroom remodeled in 2019

## Photo(s)



**Plumbing Fixtures** 

#### Update Type

Replaced

Timeframe

2-5

New tubs. New standing shower replaced in 2019

## Photo(s)



Cabinets Countertops		
Update Type	Timeframe	Description
Replaced	2-5	New countertop. New appliance
Photo(s)		



## **Room Deficiency Type**

None Observed

Additional Photos





## **Primary Bedroom**

## **F2**

#### **Room Features**

None

#### Room Update Type

None Observed

## Room Deficiency Type

None Observed

#### Additional Photos





## 5. Structure Area Summary

Level	Earth Contact	Low Level Ceiling	Attic	Finished Living Area	Total Area
Level 1	No	No	No	1373	1908
Level 2	No	No	No	1700	1700

Bedrooms	Other Rooms	Total Rooms
6	6	12
Bathrooms		
3		
6. Additional Structure		
None		
7. Car Storage		
Off Street Parking Availability		

#### Yes

## Parking Type

Туре	Count	SQFT	
Attached Garage	3	565	
Garage Conversion			

#### No

#### Photo(s)



## Attached Garage: Updates

Updated Component

None Observed

## Attached Garage: Deficiencies

Deficiency Name

None Observed

8. Property Data Collector Certification			
Collection Type	Person at subject property	Property Data Collector Name	
Onsite		Aste080401	
Person who completed property data report	Professional License Type	Professional License #	
Other		N/A	
Professional License State	Expiration Date of Certification or License		
N/A	N/A		
Property Data Collector Company			
Property Data Collector Company Name	Property Data Collector Company Address	Property Data Collector Company Address (City)	
Asteroom	48511 Warm Spring Blvd	Fremont	
Property Data Collector Company Address (State)	Property Data Collector Company Address (Zip)		
CA	94539		
Property Data Collector Contact Info	Date of Observation	Property Data Collector Date of Signature and Report	
Aste080401@yopmail.com +15108976600	2023-03-23	2023-03-26	
Property Data Collector Signature			

Eric Tsai

9. 3D Tour

Click button or scan QR code to view >


JD tour



10. Floor Plan

# 'Asteroom







FLOOR 1



FLOOR 2

GLA total: 3073.222168 sq. ft, excluded areas: 683.333313 sq. ft Floor1 1372.833374 sq. ft

$$\label{eq:constraint} \begin{split} & |((21828.76^*.3916.01)-(-3916.01*21474.76)+(21474.76^*.3875.01)-(-3916.01*21474.76)+(21474.76^*.3875.01)-(-3875.01*21364.76)+(21364.76^*.3916.01)-(-3916.01*21241.76)+(21241.76^*.4395.01)-(-395.01*21397.76)+(21397.76^*.4360.76)-(-4395.01*21397.76)+(21397.76^*.4360.76)-(-4395.01*21397.76)+(21397.76^*.4360.76)-(-4360.76)+(21481.76^*.4396.76)-(-4360.76)+(21481.76^*.4360.76)-(-4360.76)+(21487.76^*.4146.01)-(-4360.76^*21487.76)+(21828.76)+(2188.$$

Floor 17/00.383916 Sq. ft [((21092.80\*-3867.28)-(-3867.28\*20824.80)+(20824.80\*-3828.28)-(-3867.28\*20824.80)+(20824.80\*-3828.28)-(-3828.28\*20710.80)+ (20710.80\*-3867.28)-(-3828.28\*20710.80)+(20710.80\*-3867.28)-(-3867.28\*20567.80)+(20567.80\*-4375.28)-(-3867.28\*20567.80)+ (20567.80\*-4375.28)-(-4375.28\*20753.80)+(20753.80\*-4193.22)-(-4375.28\*20753.81)+(20753.81\*-4193.22)-(-4193.22\*20823.80)+ (20823.80\*-4375.28)-(-4193.22\*20823.80)+(20823.80\*-4375.28)-(-4375.28\*20961.80)+(20961.80\*-4308.28)-(-4375.28\*20961.80)+

(20961.80\*-4308.28)-(-4308.28\*21092.80)+(21092.80\*-3867.28)-(-4308.28\*21092.80))\*0.5/144] -Excluded:Garage 565.277771

|((21848.19\*-4176.18)-(-4176.18\*21513.19)+(21513.19\*-4419.18)-(-4176.18\*21513.19)+(21513.19\*-4419.18)-(-4419.18\*21848.19)+ (21848.19\*-4176.18)-(-4419.18\*21848.19))\*0.5/144| -Excluded:Stairs 32.500000

[(22650.11\*-4058.28)-(-4058.28\*22528.16)+(22528.16\*-4096.68)-(-4058.28\*22528.16)+(22528.16\*-4096.68)-(-4096.68\*22650.11)+ (22650.11\*-4058.28)-(-4096.68\*22650.11))\*0.5/144]

-Excluded:Open 85.555557

|((20445.14\*-4193.22)-(-4369.28\*20445.14)+(20445.14\*-4193.22)-(-4193.22\*20375.14)+(20375.14\*-4369.28)-(-4193.22\*20375.14)+ (20375.14\*-4369.28)-(-4369.28\*20445.14))\*0.5/144|

#### STATEMENT OF LIMITING CONDITIONS

CONTINGENT AND LIMITING CONDITIONS: The data collector's certification that appears in this report is subject to the following conditions: 1. The data collector will not be responsible for matters of a legal nature that affect either the subject property or the title to it

 The data collector will not give testimony or appear in court because of this assignment unless specific arrangements to do so have been made beforehand

3. The data collector has noted in the report any observed adverse conditions (such as, but not limited to, needed repairs, the presence of hazardous wastes, toxic substances, pest infestation, structural problems, mechanical problems, or habitability issues) and makes no guarantees or warranties, expressed or implied, regarding any unobserved conditions. Because the data collector is not an expert in the field of environmental hazards, pests, structural integrity or mechanical systems, this report must not be considered as an environmental assessment, pest inspection, or engineering report.

4. The data collector obtained the information and estimates that were expressed in this report from sources that he or she considers to be reliable and believes them to be true and correct. The data collector does not assume responsibility for the accuracy of such items furnished by other parties.

5. The data collector will not disclose the contents of this report to any individual or party other than the client or intended user, except as required by law or as directed by the client

#### DATA COLLECTOR'S CERTIFICATION:

I certify that, to the best of my knowledge and belief:

1. The statements of fact contained in this report are true and correct

2. In the development of this report I have obtained adequate information to support my unbiased professional conclusions

3. Any intentional or negligent misrepresentation(s) contained in this report may result in civil liability and/or criminal penalties including, but not limited to fine or imprisonment or both under the provisions of Title 18, United States Code, Section 1001, et seq., or similar state laws

4. When the data collection was completed onsite as designated under data collection type - I have performed a complete visual data collection of the interior and exterior areas of the subject property. I reported the condition of the improvements in factual, specific terms, I identified and reported physical deficiencies that could affect the livability, soundness or structural integrity of the property. When the data collection was completed virtually as designated under data collection type - In completion of this assignment I have utilized video technology sufficient to perform a complete and adequate visual data collection of the interior and exterior areas of the subject property. I reported the condition of the improvements in factual, specific terms, identified and reported the physical deficiencies that could affect the livability, soundness or structural integrity of the property. I reported the condition of the improvements in factual, specific terms, identified and reported the physical deficiencies that could affect the livability, soundness or structural integrity of the property.

5. My compensation is not contingent on an action or event resulting from the conclusions or use of this report

6. The information used as the basis of the conclusions within this report is adequate and deemed reliable by the data collector

7. I have adequate knowledge, training and competency to complete this assignment

8. I have not withheld any information relevant to this assignment

9. I have no present or prospective interest in the property that is the subject of this report, and I have no present or prospective personal interest or bias with respect to the participants in the transaction. I did not base, either partially or completely, my conclusions within this report, on the race, color, religion, sex, age, marital status, handicap, familial status, or national origin of either the prospective owners or occupants of the subject property or of the present owners or occupants of the properties in the vicinity of the subject property or on any other basis prohibited by law.

10. My employment and/or compensation for performing this assignment or any future or anticipated assignments was not conditioned on any agreement or understanding, written or otherwise, that I would report a predetermined specific outcome that favors the cause of any party, or the attainment of a specific result or occurrence of a specific subsequent event (such as approval of a pending mortgage loan application)

11. The lender/client may disclose or distr bute this report to: the borrower; an appraiser to utilize in the completion of an appraisal assignment; another lender at the request of the borrower; the mortgage or its successors and assigned; mortgage insurers; government sponsored enterprises; other secondary market participants; data collection or reporting services; professional appraisal organizations; any department, agency, or instrumentality of the United States; and any state, the District of Columbia, or other jurisdictions; without having to obtain the data collector's or supervisor appraiser (if applicable) consent. Such consent must be obtained before this report may be disclosed or distr buted to any other party (including but not limited to, the public through advertising, public relations, news, sales, or other media).

12. If this report was transmitted as an "electronic record" containing my "electronic signature," as those terms are defined in applicable federal and/or state laws (excluding audio and video recordings), or a facsimile transmission of this report containing a copy or representation of my signature, the report shall be as effective, enforceable and valid as if a paper version of this report were delivered containing my original hand-written signature

#### SUPERVISORY APPRAISER'S CERTIFICATION (if applicable):

The Supervisory Appraiser certifies and agrees that:

1. I directly supervised the appraiser who acted as the data collector for this assignment, have read the report, and agree with the data collector's statements, conclusions, and the data collector's certification

2. I accept full responsibility for the contents of this report including, but not limited to, the data collector's statements and conclusions and the data collector's certification

3. The data collector identified in this report is either a sub-contractor or an employee of the supervisory appraiser (or the appraisal firm), is qualified to perform this assignment, and is acceptable to perform this report under the applicable state law

4. If this report was transmitted as an "electronic record" containing my "electronic signature," as those terms are defined in applicable federal and/or state laws (excluding audio and video recordings), or a facsimile transmission of this report containing a copy or representation of my signature, the report shall be as effective, enforceable and valid as if a paper version of this report were delivered containing my original hand-written signature

## **Property Data Report**



#### 1. Information Type of PDR Dataset version LPA Key ACE+PDR 2.0 0000 Seller ID File # Additional File # 0000 PDR\_337 0000 Property Type Single Family Address Property Street Address Property Street Address (unit #) Property City

13835 SW Sandridge Dr		Tigard
Property State	Property Zip Code	Property County
Oregon	97223	Washington

#### Property Photo



## 2. Subject and Lender / Client

#### Borrower Name

Lender Contact Information

HOA Fee

\$40

#### Lender/Client Name

AMC Name

HOA Fee Annual or Monthly

Monthly

Lender/Client Address

Assignment Type (Purchase/Refi)

Refinance

Years Owned

Exterior

Date of contract

2023-03-15

#### \$0

3. Site		
Site Conditions	Site Conditions - Other Description	
Extreme Slope	Going down from the backyard.	
Street/Alley Type	Street Materials	Street Ownership
Street	Asphalt	Public
Does the property adjoin to any external factors?	External Factors Other Description	Has the property been altered or modified specifically to support or facilitate any non-residential, or income producing use?
Park, Greenbelt		None
Evidence of Dampness, Settlement and Infestation Conditions	Describe the evidence of Dampness, Settlement and infestation conditions	
No		
Site/Common Amenities	Other Site/Common Amenities Description	Site/Common Amenities Sub-Type
Fence		Fence Selections: Wood, Chain Link
Utility Type		
Electricity	Gas	Water
Public	Public	Public
Oil	Sanitary Sewer	
No	Public	
4.1 Improvements - Exterior and In		

Structure Type Primary Dwelling	Building Completion Status Existing	Occupancy Type <b>Owner</b>
Accessory Unit False	Attachment type <b>False</b>	End unit

View Type	View Description	
Residential, Woods		
Foundation Wall		
Foundation Wall Material	Foundation Wall Material Description	Foundation Wall Condition
Concrete		None
Exterior Wall		
Exterior Wall Material	Exterior Wall Material Description	Exterior Wall Condition
Other Siding	Cement Siding	None
Gutter and Downspouts		
Gutter and Downspouts Material	Gutter and Downspouts Condition	
Aluminium	None	
Roof		
Roof Surface Material	Roof Surface Material Description	Roof Surface Condition
Other Shingle	Asphalt Shingle	None
Roof Age		
1-10 years		
Window		
Window Material	Window Material Condition	Window Updates
Multi-Pane, Vinyl, Single Hung, Sliding	None	No Update
Window Update Description	Screens	Storm Sash
	Yes	No
Foundation		
Foundation type	Sump Pump Indicator	
Crawlspace	Νο	
Interior		
Heating		
Heating		
Heating Type	Heating Description	Heating Updates

Heating Update Description	Heating Damages/Defects <b>None</b>	
Cooling		
Cooling Type	Cooling Description	Cooling Update
Central Air		No Update
Cooling Update Description	Cooling Damages/Defects	
	None	
Attic		
Attic	Attic Features	Attic Features Description
Yes	Scuttle	
4.2 Improvements - Rooms Bathroom 2		Level F1
		Leventi
Interior Floors		
Interior Floors Material	Interior Floors Material Condition	Interior Floor Updates
Vinyl	None	Fully Updated
Interior Floor Update Description		
The flooring has been updated.		
Interior Walls and Ceilings		
Interior Walls and Ceilings Material	Interior Walls and Ceilings Condition	Interior Walls and Ceilings Updates
Drywall	None	No Update

Shower/Tub Surround	
Shower rub Surround	
Shower/Tub Surround Material	Shower/Tub Surround Condition
Fiberglass	None

Estimate Year of Improvement

Description of Improvement

1 - 5 years

The bathroom cabinets were updated.

#### Bathroom 2 Photo



Bedroom 2		Level F1
Interior Floors		
Interior Floors Material	Interior Floors Material Condition	Interior Floor Updates
Carpet	None	No Update
Interior Floor Update Description		
Interior Walls and Ceilings		
Interior Walls and Ceilings Material	Interior Walls and Ceilings Condition	Interior Walls and Ceilings Updates
Drywall	None	No Update
Interior Walls and Ceilings Update Description		

#### Bedroom 2 Photo



Family Room		Level F1
Interior Floors		
Interior Floors Material	Interior Floors Material Condition	Interior Floor Updates
Carpet	None	No Update
Interior Floor Update Description		
Interior Walls and Ceilings	Interior Walls and Ceilings Condition	Interior Walls and Ceilings Updates
Drywall	None	No Update
Interior Walls and Ceilings Update Description		-

## Family Room Photo



Kitchen			Level F1
Interior Floors			
Interior Floors Material	Interior Floors Material Condition	Interior Floor Updates	
Hardwood	None	No Update	
Interior Floor Update Description			

## **Interior Walls and Ceilings**

Interior Walls and Ceilings Material

Interior Walls and Ceilings Condition

None

Interior Walls and Ceilings Updates

No Update

Drywall

6

Interior Walls and Ceilings Update Description

Appliances	Appliances Other (describe)
Microwave, Refrigerator, Dishwasher, Range Oven, Disposal	
Kitchen Countertops Materials	Kitchen Cabinets Quality Rating
Laminate	Stendard Typical
Lammate	Standard Typical
	Standard Typical
Estimate Year of Improvement	Description of Improvement

#### Kitchen Photo



Dining Room		Level F1
Interior Floors		
Interior Floors Material	Interior Floors Material Condition	Interior Floor Updates
Carpet	None	No Update
Interior Floor Update Description		
Interior Walls and Ceilings		
Interior Walls and Ceilings Material	Interior Walls and Ceilings Condition	Interior Walls and Ceilings Updates
Drywall	None	No Update
Interior Walls and Ceilings Update Description		

#### Dining Room Photo



Living Room		Level F1
Interior Floors		
Interior Floors Material	Interior Floors Material Condition	Interior Floor Updates
Carpet	None	No Update
Interior Floor Update Description		
Interior Walls and Ceilings		
Interior Walls and Ceilings Material	Interior Walls and Ceilings Condition	Interior Walls and Ceilings Updates
Drywall	None	No Update
Interior Walls and Ceilings Update Description		

## Living Room Photo



Level F1

**Interior Floors** 

Interior Floors Material Hardwood	Interior Floors Material Condition	Interior Floor Updates No Update
Interior Floor Update Description		
Interior Walls and Ceilings		
Interior Walls and Ceilings Material	Interior Walls and Ceilings Condition	Interior Walls and Ceilings Updates
Drywall	None	No Update
Interior Walls and Ceilings Update Description		

#### Foyer Photo



<b>Primary Bathr</b>	oom

Interior Floors		
Interior Floors Material	Interior Floors Material Condition	Interior Floor Updates
Vinyl	None	Fully Updated
Interior Floor Update Description		
The flooring has been updated.		
Interior Walls and Ceilings		
Interior Walls and Ceilings Interior Walls and Ceilings Material	Interior Walls and Ceilings Condition	Interior Walls and Ceilings Updates
	Interior Walls and Ceilings Condition	Interior Walls and Ceilings Updates No Update

Level F2

Shower/Tub Surround Material	Shower/Tub Surround Condition
Tile	None
Estimate Year of Improvement	Description of Improvement
1 - 5 years	The bathroom cabinets were updated.

## Primary Bathroom Photo



## Primary Bedroom

### **Interior Floors**

Interior Floors Material	Interior Floors Material Condition	Interior Floor Updates
Carpet	None	No Update
Interior Floor Update Description		

Interior Walls and Ceilings		
Interior Walls and Ceilings Material	Interior Walls and Ceilings Condition	Interior Walls and Ceilings Updates
Drywall	None	No Update
Interior Walls and Ceilings Update Description		

Primary Bedroom Photo

Level F2



## Level F2 **Bedroom 6 Interior Floors** Interior Floors Material Interior Floors Material Condition Interior Floor Updates Carpet None No Update Interior Floor Update Description **Interior Walls and Ceilings** Interior Walls and Ceilings Material Interior Walls and Ceilings Condition Interior Walls and Ceilings Updates Drywall None No Update Interior Walls and Ceilings Update Description

#### Bedroom 6 Photo



**Bedroom 5** 

Level F2

**Interior Floors** 

Interior Floors Material	Interior Floors Material Condition	Interior Floor Updates
Carpet	None	No Update
Interior Floor Update Description		
Interior Walls and Ceilings		
Interior Walls and Ceilings Material	Interior Walls and Ceilings Condition	Interior Walls and Ceilings Updates
Drywall	None	No Update
Interior Walls and Ceilings Update Description		

### Bedroom 5 Photo



# **Bedroom 4**

Interior Floors		
Interior Floors Material	Interior Floors Material Condition	Interior Floor Updates
Carpet	None	No Update
Interior Floor Update Description		
Interior Walls and Ceilings		
Interior Walls and Ceilings Material	Interior Walls and Ceilings Condition	Interior Walls and Ceilings Updates
Drywall	None	No Update
Interior Walls and Ceilings Update Description		

Level F2



# Laundry Room Interior Floors Interior Floors Material Vinyl None

Interior Floors Material Condition
None

Interior Floor Updates

Interior Floor Update Description

Interior Walls and Ceilings		
Interior Walls and Ceilings Material	Interior Walls and Ceilings Condition	Interior Walls and Ceilings Updates
Drywall	None	No Update
Interior Walls and Ceilings Update Description		

### Laundry Room Photo



**Bedroom 3** 

Level F2

Level F2

**Interior Floors** 

Interior Floors Material Carpet	Interior Floors Material Condition	Interior Floor Updates <b>No Update</b>
Interior Floor Update Description		
Interior Walls and Ceilings		
Interior Walls and Ceilings Material	Interior Walls and Ceilings Condition	Interior Walls and Ceilings Updates
Drywall	None	No Update
Interior Walls and Ceilings Update Description		

# Bedroom 3 Photo



### Bathroom 3

Interior Floors		
Interior Floors Material	Interior Floors Material Condition	Interior Floor Updates
Vinyl	None	Fully Updated
Interior Floor Update Description		
The flooring has been updated.		
Interior Walls and Ceilings		
Interior Walls and Ceilings Material	Interior Walls and Ceilings Condition	Interior Walls and Ceilings Updates
Drywall	None	No Update
Interior Walls and Ceilings Update Description		

Level F2

Shower/Tub Surround Material	Shower/Tub Surround Condition
Fiberglass	None
Estimate Year of Improvement Not Updated	Description of Improvement

#### Bathroom 3 Photo



# Garage

# **Interior Floors**

Interior Floors Material	Interior Floors Material Condition	Interior Floor Updates
Finished Concrete	None	No Update
Interior Floor Update Description		

Interior Walls and Ceilings		
Interior Walls and Ceilings Material	Interior Walls and Ceilings Condition	Interior Walls and Ceilings Updates
Drywall	None	No Update
Interior Walls and Ceilings Update Description		
Garage Number of Car	Garage Square Feet	
3	565	

Level F1



# 4.3 Improvement - Summary of Main Structure

Property is not livable Indicator False	Property is not livable comment	
Are there any apparent defects or deficiencies to the electrical, plumbing systems, water or sewer that may cause them to function inadequately for their intended purpose?	Does the property have adequate access, and appropriate systems, for all seasons?	Does the property appear to be constructed to community standards, is not of poor quality, substandard or non-conforming workmanlike manner?
False	True	True
Is there any apparent fire or water damage that may compromise the livability, safety, soundness, or structural integrity of the property?		
False		
Structure Amenities		
Structure Amenities & count	Other Structure Amenities Description	Patio Selections
Fireplace, Patio, Deck, Other	Jacuzzi	Paver Brick
Fireplace Count:1		
Deck Selection		
Wood		
Structure Area Summary		
Number of stories		
2		
Finished Area Above Grade Room Count	Finished Area Above Grade Bedroom Count	Finished Area Above Grade Full Bathroom Count
11	6	3

Finished Area Abo Count	ve Grade	e Half Bath	Square Feet of Gross Living Area Above Grade						
0			3073						
	Area	Finished sq.	FT Bedroor	ms Other	rooms	Total room	n Fu	II Bathroom	Half batthroom
Floor 1	1373	1373	1		4	5		1	0
Floor 2	1700	1700	5		1	6		2	0
Above grade total	3073	3073	6	:	5	11		3	0
Basement/Below C	ement/Below Grade Access Square Feet of Basement/Below Grade Basement/Below Grade Finished 0				Below Grade F	Percent			
Number of Recrea Grade	tion roon	ns Below	Number of Be Grade	edrooms roor	ns Below	Nur	mber of	Full Bathroom	s Below Grade
0			0			0			
Number of Half Ba 0	throom E	Below Grade	Number of Ot 0	her rooms B	elow grade	e			
	Area	Finished sq. FT	Rec Rooms	Bedrooms	Other roo	oms Tota	l room	Full Bathroom	Half batthroom
Below grade total	0	0	0	0	0		0	0	0

# 4.4 Additional Structure

None

# 4.5 Car Storage

#### Car Storage Indicator

True

Parking Type	Attached to Dwelling?	Surface	Built-In to Dwelling?	Number of space	Is parking covered?	Sqaure Feet
Garage	Yes	Concrete	Yes	3	Yes	565
Driveway	Yes	Concrete	No	3	No	

# 5. Neighborhood

Property/Neighborhood Location Type

#### Suburban

6. Repair and Inpection

Required Repairs	Required Inspections	Are any parts of the subject property under construction or incomplete?
None	None	Completed
7.Energy Information		
Energy Rating Performed	Energy Rating Organization	Energy Rating Description
Renewable Energy Components Present	Identify Renewable Energy Components	Renewable Energy Additional Information
No	None	
Renewable Energy - Solar Panel Ownership		

8. Property Data Collector Certification				
Collection Type	Person at subject property	Property Data Collector Name		
Onsite		Ron Braithwaite		
Person who completed property data report	Professional License Type	Professional License #		
Other		N/A		
Professional License State	Expiration Date of Certification or License			
N/A	N/A			
Property Data Collector Company				
Property Data Collector Company Name	Property Data Collector Company Address	Property Data Collector Company Address (City)		
Asteroom	48511 Warm Spring Blvd	Fremont		
Property Data Collector Company Address (State)	Property Data Collector Company Address (Zip)			
CA	94539			
Property Data Collector Contact Info	Date of Observation	Property Data Collector Date of Signature and Report		
Ron@illuminateye.com +15032673250	2023-03-14	2023-03-15		
Property Data Collector Signature				

RonBraithwaite

9. Supervisory

Supervisory Name	Supervisory Contact Info	Supervisory
Dennis Luna	408-520-9339	2023-03-15
Supervisory State License #	Supervisory State	Supervisory
N/A	N/A	N/A
Did or did not personally observe interior and exterior of subject property	Supervisor Signature	
False	Dennis Luna	

# 10. Additional photos





















# 11. 3D Tour

Click button or scan QR code to view >

JD tour



12. Floor Plan

# 'Asteroom





FLOOR 1



GLA total: 3073.222168 sq. ft, excluded areas: 683.333313 sq. ft Floor1 1372.833374 sq. ft

|((21828.76\*-3916.01)-(-3916.01\*21474.76)+(21474.76\*-3875.01)-(-3916.01\*21474.76)+(21474.76\*-3875.01)-(-3875.01\*21364.76)+ (21364.76\*-3916.01)-(-3875.01\*21364.76)+(21364.76\*-3916.01)-(-3916.01\*21241.76)+(21241.76\*-4395.01)-(-3916.01\*21241.76)+ (21241.76\*-4395.01)-(-4395.01\*21397.76)+(21397.76\*-4360.76)-(-4395.01\*21397.76)+(21397.76\*-4360.76)-(-4360.76\*21481.76)+ (21481.76\*-4360.76)-(-4360.76\*21487.76)+(21487.76\*-4146.01)-(-4360.76\*21487.76)+(21487.76\*-4146.01)-(-4146.01\*21828.76)+ (21828.76\*-3916.01)-(-4146.01\*21828.76))\*0.5/144 Floor 1700.388916 sq. ft

 $\begin{array}{l} \label{eq:constraint} \label{eq:constraint} \end{cases} \en$ (20823.80\*-4375.28)-(-4193.22\*20823.80)+(20823.80\*-4375.28)-(-4375.28\*20961.80)+(20961.80\*-4308.28)-(-4375.28\*20961.80)+

(20961.80\*-4308.28)-(-4308.28\*21092.80)+(21092.80\*-3867.28)-(-4308.28\*21092.80))\*0.5/144 -Excluded:Garage 565.27771

|((21848.19\*-4176.18)-(-4176.18\*21513.19)+(21513.19\*-4419.18)-(-4176.18\*21513.19)+(21513.19\*-4419.18)-(-4419.18\*21848.19)+ (21848.19\*-4176.18)-(-4419.18\*21848.19))\*0.5/144 -Excluded:Stairs 32.500000

|((22650.11\*-4058.28)-(-4058.28\*22528.16)+(22528.16\*-4096.68)-(-4058.28\*22528.16)+(22528.16\*-4096.68)-(-4096.68\*22650.11)+ (22650.11\*-4058.28)-(-4096.68\*22650.11))\*0.5/144

-Excluded:Open 85.555557

|((20445.14\*-4193.22)-(-4369.28\*20445.14)+(20445.14\*-4193.22)-(-4193.22\*20375.14)+(20375.14\*-4369.28)-(-4193.22\*20375.14)+ (20375.14\*-4369.28)-(-4369.28\*20445.14))\*0.5/144

#### STATEMENT OF LIMITING CONDITIONS

CONTINGENT AND LIMITING CONDITIONS: The data collector's certification that appears in this report is subject to the following conditions: 1. The data collector will not be responsible for matters of a legal nature that affect either the subject property or the title to it

 The data collector will not give testimony or appear in court because of this assignment unless specific arrangements to do so have been made beforehand

3. The data collector has noted in the report any observed adverse conditions (such as, but not limited to, needed repairs, the presence of hazardous wastes, toxic substances, pest infestation, structural problems, mechanical problems, or habitability issues) and makes no guarantees or warranties, expressed or implied, regarding any unobserved conditions. Because the data collector is not an expert in the field of environmental hazards, pests, structural integrity or mechanical systems, this report must not be considered as an environmental assessment, pest inspection, or engineering report.

4. The data collector obtained the information and estimates that were expressed in this report from sources that he or she considers to be reliable and believes them to be true and correct. The data collector does not assume responsibility for the accuracy of such items furnished by other parties.

5. The data collector will not disclose the contents of this report to any individual or party other than the client or intended user, except as required by law or as directed by the client

#### DATA COLLECTOR'S CERTIFICATION:

I certify that, to the best of my knowledge and belief:

1. The statements of fact contained in this report are true and correct

2. In the development of this report I have obtained adequate information to support my unbiased professional conclusions

3. Any intentional or negligent misrepresentation(s) contained in this report may result in civil liability and/or criminal penalties including, but not limited to fine or imprisonment or both under the provisions of Title 18, United States Code, Section 1001, et seq., or similar state laws

4. When the data collection was completed onsite as designated under data collection type - I have performed a complete visual data collection of the interior and exterior areas of the subject property. I reported the condition of the improvements in factual, specific terms, I identified and reported physical deficiencies that could affect the livability, soundness or structural integrity of the property. When the data collection was completed virtually as designated under data collection type - In completion of this assignment I have utilized video technology sufficient to perform a complete and adequate visual data collection of the interior and exterior areas of the subject property. I reported the condition of the improvements in factual, specific terms, identified and reported the physical deficiencies that could affect the livability, soundness or structural integrity of the property. I reported the condition of the improvements in factual, specific terms, identified and reported the physical deficiencies that could affect the livability, soundness or structural integrity of the property.

5. My compensation is not contingent on an action or event resulting from the conclusions or use of this report

6. The information used as the basis of the conclusions within this report is adequate and deemed reliable by the data collector

7. I have adequate knowledge, training and competency to complete this assignment

8. I have not withheld any information relevant to this assignment

9. I have no present or prospective interest in the property that is the subject of this report, and I have no present or prospective personal interest or bias with respect to the participants in the transaction. I did not base, either partially or completely, my conclusions within this report, on the race, color, religion, sex, age, marital status, handicap, familial status, or national origin of either the prospective owners or occupants of the subject property or of the present owners or occupants of the properties in the vicinity of the subject property or on any other basis prohibited by law.

10. My employment and/or compensation for performing this assignment or any future or anticipated assignments was not conditioned on any agreement or understanding, written or otherwise, that I would report a predetermined specific outcome that favors the cause of any party, or the attainment of a specific result or occurrence of a specific subsequent event (such as approval of a pending mortgage loan application)

11. The lender/client may disclose or distr bute this report to: the borrower; an appraiser to utilize in the completion of an appraisal assignment; another lender at the request of the borrower; the mortgage or its successors and assigned; mortgage insurers; government sponsored enterprises; other secondary market participants; data collection or reporting services; professional appraisal organizations; any department, agency, or instrumentality of the United States; and any state, the District of Columbia, or other jurisdictions; without having to obtain the data collector's or supervisor appraiser (if applicable) consent. Such consent must be obtained before this report may be disclosed or distr buted to any other party (including but not limited to, the public through advertising, public relations, news, sales, or other media).

12. If this report was transmitted as an "electronic record" containing my "electronic signature," as those terms are defined in applicable federal and/or state laws (excluding audio and video recordings), or a facsimile transmission of this report containing a copy or representation of my signature, the report shall be as effective, enforceable and valid as if a paper version of this report were delivered containing my original hand-written signature

#### SUPERVISORY APPRAISER'S CERTIFICATION (if applicable):

The Supervisory Appraiser certifies and agrees that:

1. I directly supervised the appraiser who acted as the data collector for this assignment, have read the report, and agree with the data collector's statements, conclusions, and the data collector's certification

2. I accept full responsibility for the contents of this report including, but not limited to, the data collector's statements and conclusions and the data collector's certification

3. The data collector identified in this report is either a sub-contractor or an employee of the supervisory appraiser (or the appraisal firm), is qualified to perform this assignment, and is acceptable to perform this report under the applicable state law

4. If this report was transmitted as an "electronic record" containing my "electronic signature," as those terms are defined in applicable federal and/or state laws (excluding audio and video recordings), or a facsimile transmission of this report containing a copy or representation of my signature, the report shall be as effective, enforceable and valid as if a paper version of this report were delivered containing my original hand-written signature