

# Disaster Inspection



# Disaster Form

Is the property viewable?	Attached
Degree of Damage to Subject	No damage
Damage is likely reparable?	No damage
Overview of Observed Damage	No Damage
Cause(s) of Damage	None
Location	Urban
Access to neighborhood	Fully Accessible
Level of Neighborhood Inspection:	Fully Viewable from Streets
Subject Property Habitability:	Apparently Habitable

# Property Photos



Front



Front Right

# Property Photos



Front Left



Street

# Property Photos



Street





Address Verification

# Property Photos



Additional Front



Philadelphia, PA 19136, USA